

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Form Approved.  
Budget Bureau No. 42-R1424

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐  
2. NAME OF OPERATOR  
El Paso Natural Gas Company  
3. ADDRESS OF OPERATOR  
Box 289, Farmington, New Mexico 87401  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1020' N, 980' E  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:  
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  
TEST WATER SHUT-OFF ☐ ☐  
FRACTURE TREAT ☐ ☐  
SHOOT OR ACIDIZE ☐ ☐  
REPAIR WELL ☐ ☐  
PULL OR ALTER CASING ☐ ☐  
MULTIPLE COMPLETE ☐ ☒  
CHANGE ZONES ☐ ☐  
ABANDON\* ☐ ☐  
(other) ☐ ☐

5. LEASE  
SF 080669  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
San Juan 27-4 Unit  
8. FARM OR LEASE NAME  
San Juan 27-4 Unit  
9. WELL NO.  
121 (FM)  
10. FIELD OR WILDCAT NAME  
Blanco M.V. - Tapacito P.C.  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 18, T-27-N, R-4-W, NMPM  
12. COUNTY OR PARISH  
Rio Arriba  
13. STATE  
New Mexico  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6809' Gr.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The following work was done to dually complete well:

8-11-78: Pulled tubing. Set bridge plug at 4116' and pressure tested to 3500#, held O.K. Perforated Pictured Cliffs formation 3678-86, 3694-3702, 3712-29, 3729-39, 3785-93' w/16 SPZ. Fraced with 60,000# 10/20 sand and 65,000 gallons water. Dropped 4 sets of 16 balls each. Flushed with 6300 gallons water. Ran two sets of production tubing.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Brad J. J. J. TITLE Drilling Clerk DATE November 17, 1978

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

