APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE SF 080675 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 27-4 Unit 8. FARM OR LEASE NAME
1. oil gas K other	San Juan 27-4 Unit 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company	132 (MD)  10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR  Box 289, Farmington, New Mexico 87401  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Blanco MV, Basin Dakota  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27, T-27-N, R-4-W N.M.P.M.
AT SURFACE: 1150'N, 1/25'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7229' GL
REQUEST FOR APPROVAL TO:  SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and
0-29-79: TD 8549'. Ran 56 joints 4 1/2", 11.6#, N-8 6749-8549'. Float collar set at 8542'. Ce WOC 18 hours.	O casing liner, 1800'. set mented w/325 cu. ft. cement.
Subsurface Safety Valve: Manu. and Type	Set @
18. I hereby certify that the foregoing is true and correct	

\*See Instructions on Reverse Side

(This space for Federal or State office use)

TITLE Drilling Clerk DATE October 29, 1979

DATE