	,			ı		
Form 9-33!		UNITED STATES	SUBMIT IN TRIPLICA	TE* Form a	approved. Bureau No. 42-R1424.	
(May 1963)	DEPAR	TMENT OF THE INTER	RIOR (Other instructions on verse side)	5. LEASE DESIGN	NATION AND SERIAL NO.	
		GEOLOGICAL SURVEY		NM 03	547	
		STICEC AND DEDODIC	ON WELLC		LLOTTEE OR TRIBE NAME	
(Do not use	this form for pro	OTICES AND REPORTS  posals to drill or to deepen or plug  ICATION FOR PERMIT—" for such	back to a different reservoir.			
1.	Use "APPL	MCATION FOR PERMIT— for such	proposais.)	7. UNIT AGREEM	ENT NAME	
OIL GAS	S LL X OTHER	1			<u> </u>	
2. NAME OF OPERATOR					SE NAME	
Caulkins Oil Company					Breech "F"	
3. ADDRESS OF OPERATOR						
Post Office Box 780, Farmington, New Mexico					48	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)					10. FIELD AND POOL, OR WILDCAT	
At surface					South Blanco	
1050 from the South and 850 from the East					11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
14. PERMIT NO.		15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR	1	
		6666 Gr.	-	Rio Arr	iba   New Mexico	
16.	Check	Appropriate Box To Indicate TENTION TO:		or Other Data		
TEST WATER SE	AUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	X REPA	IRING WELL	
FRACTURE TREA	T -	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTE	RING CASING	
SHOOT OR ACIDI		ABANDON*	SHOOTING OR ACIDIZING	ABAN	DONMENT.	
REPAIR WELL		CHANGE PLANS	(Other)			
(Other)			(Nore: Report re Completion or Rec	sults of multiple components of multiple components on Report and	Log form.)	
17. DESCRIBE PROPOS	ED OR COMPLETED	OPERATIONS (Clearly state all pertinectionally drilled, give subsurface lo	ent details, and give pertinent d	lates, including estima ertical depths for all	ted date of starting any markers and zones perti-	
nent to this w	ork.) *	<b>3 3 3 3 3 3 3 3 3 3</b>				
Spudded	1.30 AM.	7-24-75 Drilled to	TD 150. Ran 150'	8 5/8" 24# J-	-55 casing	
to 1501 as	nd coments	ed with 100 sacks. C	ement circulated.	1.1		
				1987年1987		
Plug dow	'n 11:50 AW	1. 7-24-75.	04 for 30 minutes	No decrease	in pressure	
7-25-75	Tested St	urface casing with 50	Of 101 30 illinutes.	140 0001005	, in probbator	
				두 글론하다	*	
				· · · · · · · · · · · · · · · · · · ·		
				139 ± 1		
				1 3 7 7		
					C 104.	
				/ A	Se COLL 3	
				<b>\</b>	" O'CT 3-/	
					DI DI	
	$\overline{}$					
18. I hereby certify	that the foregoi	ng is true and correct	C 4 2 4	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	7-27-75	
SIGNED 1	Lear les	Leque TITLE	Superintendent	DATE _	1-41-13	

\*See Instructions on Reverse Side

DATE \_

TITLE ...

(This space for Federal or State office use)