

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-verse side)

Form approved  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 03547	
2. NAME OF OPERATOR Caulkins Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Post Office Box 780, Farmington, New Mexico		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  1000' From the West and 990' from the South		8. FARM OR LEASE NAME Breech F	
14. PERMIT NO.		9. WELL NO. 545	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6602 Gr.		10. FIELD AND POOL, OR WILDCAT South Blanco	
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Section 35 27N 6W	
		12. COUNTY OR PARISH Rio Arriba	13. STATE New Mex

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spud at 12:00 Noon 5-5-77

Drilled 12 1/4" hole to 104'.

Cemented 8 5/8" 24# J-55 casing at 104' with 100 sacks class B cement containing 2 % CaCl. Plug down @ 4:30 pm 5-5-77. Cement did circulate to surface.

Surface pipe tested with 500# 5-6-77. No decrease in pressure.



18. I hereby certify that the foregoing is true and correct

SIGNED Lawrence Blacett

TITLE Production Foreman

DATE 5-9-77

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side