UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLIC
(Other instructions o
verse side)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

Form approved.
Budget Bureau No. 42-R142

5. LEASE DESIGNATION AND SERIAL NO.

Joint Venture Agreement

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Apache-JVA

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Blanco-Mesaverde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28-T27N-R2W

1.

OIL WELL ☐   GAS WELL ☒   OTHER

2. NAME OF OPERATOR

Palmer Oil & Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 2564, Billings, Montana 59103

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

NE¼NW¼SW¼   850' FWL & 790' FSL

14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	7335' KB	Rio Arriba	New Mexico

16.   Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) ___ Status Report
(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐
ALTERING CASING
ABANDONMENT* ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.) *

Well was spudded at 9:30 PM 9/20/77. Ran 328' of 9-5/8" casing and cemented with 250 sx.

Ran 98 joints 7" 20# to 3961' and cemented with 700 sx.

Total Depth 7455' KB. Ran 4½" production liner from 3637.67' to 6274.03' KB. (323.31'
overlap in 7" casing).

Waiting on completion.

OCT 2 5 1977

18. I hereby certify that the foregoing is true and correct

SIGNED _Grace E. Brown_   TITLE __Assistant Secretary__   DATE __10/4/77__

(This space for Federal or State office use)

APPROVED BY _____   TITLE _____   DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side