UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Form Approved. Budget Bureau No. 4281424
. [5. LEASE
	Contract 93
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Jicarilla Apache
rent	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
	Jicarilla 93
	9. WELL NO.
	. 7
	10. FIELD OR WILDCAT NAME
	Gavilan Pictured Cliffs 11. SEC., T., R., M., OR BLK. AND SURVEY OR
17	AREA Sec 32 T27N R3W
	12. COUNTY OR PARISH New Mexico
	14. API NO.
ICE,	
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7117' GR
:	
	(NOTE: Report results of multiple completion or zone change on Form 9-330.)

		oldarilla Mudelle	
SUNDRY N	OTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
Do not use this form eservoir, Use Form 9-	for proposals to drill or to deepen or plug back to a different 331–C for such proposals.)	8. FARM OR LEASE NAME	
	00	Jicarilla 93	
	as 🗓 other	9. WELL NO.	
2. NAME OF OP	FRATOR	7	
orthwest Pi	peline Corporation	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF	OPERATOR	Gavilan Pictured Cliffs	
O Box 90,	Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF	WELL (REFORT LOCATION CLEARLY. See space 17	AREA	
below.)		Sec 32 T27N R3W	
AT SURFACE:	145C' FNL & 1055' FWL	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD		Rio Arriba New Mexico	
AT TOTAL DE	P(H:	14. API NO.	
5. CHECK APPRO	OPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR	OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
•	·	7117' GR	
EQUEST FOR AP			
EST WATER SHU			
RACTURE TREAT			
EPAIR WELL		(NOTE: Report results of multiple completion or zone	
ULL OR ALTER	CASING 🗒	change on Form 9-330.)	
ULTIPLE COMPL	ETE 🗍		
HANGE ZONES			
BANDON*			
other <u>) "s</u>	ummary"		
including estimates and measured and 9-26-77	ROPOSED OR COMPLETED OPERATIONS (Clearly statemated date of starting any proposed work. If well is don't rue vertical depths for all markers and zones pertiner. Spudded 12 1/4" surface hole. Ran	lirectionally drilled, give subsurface locations and nt to this work.)*	
3-20-77	Cmted w/ 90 sks, circ 4 bbls.		
10-18-77	Started drlg 6 3/4" hole.		
10-19-77	Pressure tested BOP @ 600 psi for	30 min. held OK.	
10-25-77	Ran I-ES & GR Density logs. Ran 4	080! of 2 7/8" csg set @ 4091".	
10-25-77	Cmted w/ 130 sks Cl"B". Good circ	Pressure tested csg to	
	3500 psi, held OK. Released rig @		
	temp survey @ 2800'.		
	temp burvey & root .		
Subsurface Safety	Valve: Manu. and Type	Set @ Ft	
	ly that the foregoing is true and correct		
SIGNED 1	TITLE Production Cl	erk Nov. 28, 1977	
	(This space for Federal or State of	fice use)	
APPROVED BY	TITLE	DATE	
CONDITIONS OF AF		- TO GIVE	

*See Instructions on Reverse Side

DEC 2 1977