5. LEASE

John S

UNITED STATES

DEPARTMENT OF THE INTERIOR	SF 078840
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
THE PERCENCE ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	San Juan 28-7 Unit
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	San Juan 28-7 Unit
1. oil gas well other	9. WELL NO.
well well other 2. NAME OF OPERATOR	110
EL PASO NATURAL GAS CO.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
BOX 289, FARMINGTON, NEW MEXICO	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 19, T-27-N, R-7
AT SURFACE: 1450'S, 1450'W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6568' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone
REPAIR WELL ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	
ABANDON*	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
(other)	(1982년 - 1984년 - 1984년 - 1984년 - 1984
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined 10/23/78: Spudded well. Drilled surfact 10/24/78: Ran 5 joints 9 5/8", 36# KS Seemented with 224 cu. ft. cement. Circu held 600#/30 minutes.	ce hole. surface casing, 205' set at 221'.
Subsurface Safety Valve: Manu. and Type	sollo COTT. 3 Ft
SIGNED 1 D. Duas TITLE Drilling Cle	rk date <u>10/25/78</u>
(This space for Federal or State of	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE JOB TO THE TOTAL PARTY OF THE PARTY OF
•	007 3 0 1073

*See Instructions on Reverse Side