APPROVED BY ________CONDITIONS OF APPROVAL, IF ANY:

Smar :

UNITED STATES

		Budget	Bureau	No. 42-R14	2
EASE	٠.				_

DEPARTMENT OF THE INTERIOR	5. LEASE SF 079367-B		
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 28-6 Unit 8. FARM OR LEASE NAME		
1. oil gas x other 2. NAME OF OPERATOR	San Juan 28-6 Unit 9. WELL NO. 70A 10. FIELD OR WILDCAT NAME Blanco Mesa Verde 11. SEC., T., R., M., OR BLK. AND SURVEY OR		
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401			
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 960'N, 1120'W AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 25, T-27-N, R-6-W N.M.P.M. 12. COUNTY OR PARISH Rio Arriba New Mexico		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6572 G.L.		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	lirectionally drilled, give subsurface locations and		
9-20-79: Spudded well. Drilled surface hole. Ran 5 j casing 206' set at 220'. Cemented w/224 cu. WOC 12 hours;held 600#/30 minutes.	oints 9 5/8", 36#, KS surface ft. cement. Circulated to surface.		
Subsurface Safety Valve: Manu. and Type	Set @Ft.		
18. I hereby certify that the foregoing is true and correct SIGNED Drilling C	lerk DATE September 21, 1979		

_ DATE _