## HAITED STATES

DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE SF-080673 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME  San Juan 27-4 Unit  8. FARM OR LEASE NAME
1. oil gas	San Juan 27-4 Unit  9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company	15A  10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, NM 87401	Tapacito PC Ext. & Blanco MV  11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1520'S, 790'E  AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 6, T-27-N, R-4-W  NMPM  12. COUNTY OR PARISH Rio Arriba New Mexico  14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Ferm 9-330.)  e all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and to this work.)*  ediate casing 4164' set at 4174'.  ediate casing 4164' set at 4774'.
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	Set @
SIGNED MARY SHAMMED TITLE Drilling Cle	rk Sept. 22, 1980
(This space for Federal or State offi	<del></del>
APPROVED BY TITLE TITLE	DATE