Form 9-331 Dec. 1973

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

	Form Approved. Budget Bureau No. 42–R1424
5. LEASE	
SF-0806	73
6. IF INDIAN, ALI	LOTTEE OR TRIBE NAME
7. UNIT AGREEM	IENT NAME
San Juan	27-4 Unit
8. FARM OR LEA	SE NAME
San Juan	27-4 Unit
9. WELL NO.	
124	<u>A</u>
10. FIELD OR WIL	
	PC & Blanco MV
	1., OR BLK. AND SURVEY OR
AREA Sec.	8,T-27-N, R-4-W
	NMPM
	PARISH 13. STATE
Rio Arriba	New Mexico
14. API NO.	
15 5 5 5 6 6 6 6 6	
	(SHOW DF, KDB, AND WD)
6771'	GL
	ilts of multiple completion or zone Form 9–330.)
te all pertinent detai	ls, and give pertinent dates
firectionally drilled, g	ive subsurface locations and

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) gas well X well other 2. NAME OF CPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.) **&05**'N, 1575'W AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta

including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertinent to this work.)*

9-17-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, 66-S surface casing 232' set at 246'. Cemented w/ 224 cu. ft. cement. Circ. to surface. WOC 12 hours; held 600#/30 minutes.

Subsurface Safety Valve: Manu. and Type		Set @		
18. I hereby certify that the foregoing i				
SIGNED / LAPY Strady	eld TITLE Drilling	g Clerk DATE	Sept. 22,	1980
	(This space for Federal or S	tate office use)	· · · · -	
APPROVED BY	TITLE	DATE		
	00	C .		