(other)

UNITED STATES DEPARTMENT OF THE INTERIOR


5.	LEASE	
	SF	079491

6.	IF INDIAN.	ALLOTTEE O	R TRIRE NAME

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME San Juan 27-5 Unit
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME San Juan 27-5 Unit'
1. oil gas well other	9. WELL NO. 105E
2. NAME OF OPERATOR El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME Basin Dakota
3. ADDRESS OF OPERATOR P.O. Box 209, Farmington, NM	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1190'S, 1740'E	AREA Sec. 11, T-27-N, R-5- NMPM
AT SURFACE: AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	LEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ARANDON*	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PRTD 8695'. Tested Casing to 4000#, OK. Perfed: 8470,8478,8486,8493,8588,8594,8600,8649,8657,8663,8670,8678' W/1 SPZ. Fraced w/ 155,000# 20/40 sand, 36,550 gal. wtr. 5-16-81.



Section Two

Subsurface Safety Valve: Mar	nu. and Type	Set @				
18. I hereby certify that the f	oregoing is true and correct					
SIGNED V.	oregoing is true and correct	erk _{DATE} May 21, 1981				
(This space for Federal or State office use)						
APPROVED BY	ANY:	DATE				

*See Instructions on Reverse Side