Rest.

1 1 - 1

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 079360 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Rincon Unit 8. FARM OR LEASE NAME
1. oil gas XX other	Rincon Unit 9. WELL NO.
2. NAME OF OPERATOR El Paso Natural Gas Company	238 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, NM 87401	Largo Chacra Ext. 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1610'N, 1520'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 22, T-27-N, R-7-W NMPM 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	5. ELEVATIONS (SHOW DF, KDB, AND WD) 6550 GL GWOTE Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent.)	lirectionally drilled, give subsurface locations and
5-26-81: Spudded well. Drilled surface hole. Ran 3 surface casing 122' set at at134'. Cemented surface. WOC 12 hours; held 600#/30 minutes.	joints of 8 5/8", 24#, J-55 w/ 106 cf. cement. Circ. to JUN 4 OIL CON. DIST.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	-
	rk DATE May 27, 1981
(This space for Federal or State office use)	

*See Instructions on Reverse Side