UNITED STATES

DEPARTMENT OF THE INTERIOR	SF 080668
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME San Juan 27-4 Unit
1 oil — gas —	8. FARM OR LEASE NAME San Juan 27-4 Unit
well well other Abandoned Location 2. NAME OF OPERATOR	9. WELL NO. 1992 1 957 97 9888 9 9 858
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Basin Dakota
Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, T-27-N, R-4-W
below.) AT SURFACE: 1815' S, 400' W	N M P M 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Rio Arriba New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6796' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF:	
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	irectionally drilled, give subsurface locations and
This location has been restored and is rea	dy for your inspection.
Hú	Rescued Satisfactory
OIL	PECEIVED JUL 1 3 1981
Subsurface Safety Valve: Manu. and Type	DIST. 3 Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNEDTITLE _Drilling C	lerkdate 6-10-80
(This space for Federal or State off	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	D ₁
	AFPROVED
	1111 1 0 1981

NMOCC

G DISTRIC' ENGINEFA