

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF 079527A
2. NAME OF OPERATOR Consolidated Oil & Gas, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR PO Box 2038, Farmington,, NM 87499		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1124' FNL & 1963' FEL (NW/NE)(B)		8. FARM OR LEASE NAME CHAMPLIN
14. PERMIT NO. API #30-039-23528		9. WELL NO. 4E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7077'GR, 7090'KB		10. FIELD AND POOL, OR WILDCAT Basin Dakota/ BS Mesa Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 35, T27N, R4W
		12. COUNTY OR PARISH Rio Arriba
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANE ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-11-85 While swabbing, swab stuck in hole.
1-12/85 Fishing & cleaning out paraffin.
1-29-85 Re-ran 1-1/2", 2.9#, J-55, IJ tbg landed @ 8149', seating nipple @ 8115'.
1-30/2-1 Cleaning up paraffin. Cleaning up to test.
4-13/14 Installed production equipment.

18. I hereby certify that the foregoing is true and correct

SIGNED Barbara C. Rex

TITLE Engineering Technician DATE 4-22-85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

*See Instructions on Reverse Side