

F. Loc. 850/N; 790/E Elev. 6742 GL Spd. _____ Cu. ft. _____ Comp. _____ TD _____ PB _____
Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. _____ Gas _____
MCF/D After _____ Hrs. SICIP _____ PSI After _____ Days GOR _____ 1st Del. _____ Oil _____

TOPS		NIID	X	Well Log	TEST DATA							
Ojo Alamo		C-103	/	Plot	X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104		Electric Log								
Fruitland				C-122								
Pictured Cliffs		Ditr		Dfo								
Chacra		Datr		Dac								
Cliff House												
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												

Rincon Unit #284

A-26-27N-07W

UNION OIL CO. OF CALIF.

E/340.56

Acres

Rincon Unit #284

A-26-27N-07W

UNION OIL CO. OF CALIF.

E/340.56
AcresP
o
o

BasinFrCoal Co. RA S 26 127N R 07W U A Oper Union Oil Co. of Cal. Lse. Rincon Unit No. 284