UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

	EDOW KORPOVED
ĺ	Budget Buleau No. 1004-0135 LExpires March 31, 1993
	Expires March 31, 1993

10 DEST DRIVE, STE. 100W MIDLAND, TX 79705 915-686-5424 LOCATION OF WELL (Footage, Sec., T. R. M., or Survey Description) 1170' FNL - 1842' FWL, SEC. 11, T-27-N, R-07-W UNIT "C" CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION Notice of Intent Subsequent Report Recompletion Non-Routine Fracturing Plugging Back Casing Repair Other: spud & cement report Other: spud & cement report Other: spud & cement returns 18 bbls, 83.5 sks. Floats held. Bumped plug at 07:00 a.m. on 9/12/97 with 400 psi. 9/12/97 Spudded well. Drilled surface hole. Ran 5 joints 9-5/8", 35#, 8rd ST & C, K-55 casing. Landed at 285'. Cement with 280 sks. Class B cement with 3% CaCl2 and 25 libsk Cello Flake. Displaced 18.8 bbls of H20. Cement returns 18 bbls, 83.5 sks. Floats held. 9/14/97 Ran 77 joints 7', 23# K-55, ST & C, 8rd, casing, landed @ 3501'. Cement with 490 sks of 65/35 POZ, Class B w/ 8% Gel, 2% CaCl2 .25#/sk Cello Flake, Displaced with 137 bbl of H20. 36 cement returns 36bbls, 9.57 sxs. with muddy returns. Floats held. Plug didn't bump. Floats held w/ 1000 PSI final lift. Displace 4 bbl over displacements. Floats held. Plug didn't bump. Floats held w/ 1000 PSI final lift. Displace 4 bbl over displacements. Floats held. Plug didn't bump. Floats held w/ 1000 PSI final lift. Cement with 525 sks of 50/50 POZ Class B w/ 4% Gel, 2% KCL, 300% FL-52, 300% CD-32, 6:25b/sk Gilsonite, .25b/sk Cello Flake. Followed by 105 sks of Class H w/ 750% FL-62, 250% SM, 200% CD-32. Displaced with 171 bbls of water with partial returns. No cement returns. Floats held. Check floats w/ 1400 PSI. Glass Held. Plug didn't bump on 09/23/97. ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMO.	BUREAU OF LAND MANAGEMENT	5. LEASE DESIGNATION AND SERIAL NO.	
SUBMIT IN TRIPLICATE SUBMIT IN TRIPLICATE		SF-079294 SEC 78773	
Do not use this form for proposals to drill or to deepen or reentry, to & different resemblin. Submit in TRIPLICATE	SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUBMIT IN TRIPLICATE SUBMIT IN TRIPLICATE OTHER SUBMIT IN TRIPLICATE OTHER SUBMIT IN TRIPLICATE OTHER SUBMIT IN TRIPLICATE OTHER SUBMIT IN TRIPLICATE TO TRIPLICATE SUBMIT IN TRIPLICATE S			
SUBMIT IN TRIPLICATE TYPE OF WELL GAS WELL OTHER S. WELL RAME AND NO. #124M MALE OF OPERATOR CONOCO INC. ADDRESS AND TELEPHONE NO. 10. PELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. FIELD AND POOL, OR EXPLORATORY AREA BLANCO MY/BASIN DAKOTA 11. COUNTY OR PARREN, STATE 11. FOUNTY OR PARREN, STATE 11. COUNTY OR PARREN, STATE 11. FOUNTY OR PARREN, STATE 11. COUNTY OR PAR			
SUBMIT IN TRIPLICATE San Juan 28-7 Unit 8. WELL NAME AND NO. WELL GAS WELL OTHER		7. IF UNIT OR CA. AGREEMENT DESIGNATION	
TYPE OF WELL OIL WELL GAS WELL OTHER #124M NAME OF OPERATOR CONOCO INC. ADDRESS AND TELEPHONE NO 10 DEST DRIVE STE: 100W MIDLAND, TX 79705 915-688-5424 10 DEST DRIVE STE: 100W MIDLAND, TX 79705 915-688-5424 1170' FNL - 1842' FWL, SEC. 11, T-27-N, R-07-W UNIT "C" RIVER OF SUBMISSION TYPE OF SUBMISSION Notice of Inlent Of Subsequent Report Of Inlent Of	SUBMIT IN TRIPLICATE VIOLENCE		
OIL WELL GAS WELL OTHER SAME STATE SAME SAME SAME SAME SAME SAME SAME SAM	TYPE OF WELL		
NAME OF OPERATOR CONOCO INC. 30-039-20991		#124M	
CONOCO INC. ADDRESS AND TELEPHONE NO 10. FEEL PHONE NO 10. FEEL AND POOL, OR EXPLORATORY AREA BLANCO MV/BASIN DAKOTA 11. COUNTY OR PARSH, STATE RIO ARRIBA, NM 11. COUNTY OR PARSH, STATE RIO AR			
ADDRESS AND TELEPHONE NO. 10 DEST DRIVE. STE. 100W MIDLAND, TX. 79705 915-686-5424 1170' FNL - 1842' FWL, SEC. 11; T-27-N, R-07-W UNIT "C" 1170' FNL - 1842' FWL,	· · · · · · · · · · · · · · · · · · ·	30-039 -2099 1 35623	
10 DEST DRIVE STE. 100W MIDLAND, TX 79705 915-686-5424 ILCATION OF WELL (Forbige, Sec., T. R. M. or Survey Description) 11. COUNTY OR PARISH, STATE RIO ARRIBA, NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Subsequent Report IDDITED BY Plugging Back Final Abandonment, Notice Casing Repair			
11. COUNTY OR PARISH, STATE		BLANCO MV/BASIN DAKOTA	
2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION. Notice of Intent Subsequent Report Subsequent Report Subsequent Report Claimy Back Plugging Back Non-Routine Fracturing Plugging Back Non-Routine Fracturing Non-Routine Fracturing Classing Repair Conversion to Injection Dispose Water Other: Spud & cement report Other: Spud & cement returns 18 bbis, 83.5 sks. Floats held. Bumped plug at 07:00 a.m. on 91/2197 with 400 psi. 9/12/97 Spudded well. Drilled surface hole. Ran 5 joints 9-5/8*, 36#, 8rd ST 8 C, K-55 casing. Landed at 285°. Cement with 280 sks. Class B cement with 3% CaCl2 and 25 lbisk Cello Flake. Displaced 18.8 bbis of 120. Cement returns 18 bbis, 83.5 sks. Floats held. Bumped plug at 07:00 a.m. on 91/2197 with 400 psi. 9/14/97 Ran 77 joints 7*, 23# K-55, ST 8 C, Ard: casing, landed @ 3501*. Cement with 490 sks of 65/35 POZ, Class B w/ 8% Gel, 2% CaCl2 25#/sk Cello Flake. Displaced with 137 bbis of 120. Seement returns 36bbis, 957 sxs., with muddy returns. Floats held. Plug didn't bump. Floats held w/ 1000 PSi final lift. Displace 4* bbis of 50/50 POZ Class B w/ 4% Gel, 2% KC. 2009 K-CD-32. Displaced with 121.5 bbis of water with partial returns. No cement returns. Floats held. Check floats w/ 1400 PSi, floats held. Plug didn't bump on 09/23/97. 9/23/97 ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMC. ACCEPTED FOR HELOADD	LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description)		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF SUBMISSION TYPE OF SUBMISSION Recompletion Notice of Intent Subsequent Report Final Abandonment Notice Final Abandonment Notice Casing Repair Altering Casing Altering Casing Conversion to lipiction Dispose Water Multi-Report Submission (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) 9/12/97 Spudded well. Drilled surface hole. Ran 5 joints 9-5/8*, 36#, 8rd ST & C, K-55 casing. Landed at 285'. Cement with 280 sks. Class B cement with 3% Cacl/2 and .25 lb/sk Cello Flake. Displaced 18.8 bibs of H20. Cement returns 18 bibs, 83.5 sks. Floats held. Bumped plug at 07:00 a.m. on 9/12/97 with 400 psi. 9/14/97 Ran 77 joints 77, 23# K-55, ST & C, 8rd, casing, landed @ 3501'. Cement with 490 sks of 65/35 POZ, Class B w/ 8% Gel, 2% Cac 25/4/sk Cello Flake, 6.25#/sk Gilsonite. Followed by 115 sks of Class B w/ 2% Cacl/2.25#/sk Cello Flake. Displaced with 137 bbi of H20, 36 cement returns 36bbis, 95.7 sxs, with muddy returns. Floats held. Plug didn't bump. Floats held w/ 1000 PSi final lift. Displace 4/ bbi over displacement. 9/23/97 Ran 32 joints 4-1/2*, 11.60#, K-55, 8rd LT&C casing. Ran 150 joints 4-1/2* 10.50#, K-55, 8rd ST&C casing. Landed at 77/16. Cement with 525 sks of Class B w/ 50% FL-62, 250% SM. 2000 CD-32. Displaced with 121.5 bibs of water with partial returns. No cement returns. Floats held. Check floats w/ 1400 PSi, floats held. Plug didn't bump on 09/23/97. 9/23/97 ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMC. DATE DATE DATE DATE DATE Conditions of approval, if any:		RIO ARRIBA, NM	
TYPE OF SUBMISSION. TYPE OF ACTION Notice of Intent Change of Plans New Construction New Construct		<u> </u>	
Abandonment Abandonment Change of Plans New Construction Non-Routine Fracturing Plugging Back Non-Routine Fracturing Water Shut-Off Altering Casing Dispose Water Dispose			
Subsequent Report C	TYPE OF SUBMISSION TYPE	OF ACTION	
Subsequent Report C	Notice of Intent D E Abandonment	Change of Plans	
Subsequent Report UC	Recompletion		
Gasing Repair Altering Casing Altering Casing Conversion to Injection Dispose Water		Non-Routine Fracturing	
Altering Casing	Final Abandonment Notice Casing Repair	Water Shut-Off	
Other: spud & cement report Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of staring any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) 9/12/97 Spudded well. Drilled surface hole. Ran 5 joints 9-5/8', 36#, 8rd ST 8 C, K-55 casing. Landed at 285'. Cement with 280 sks. Clas B cement with 3% CaCl2 and .25 lb/sk Cello Flake. Displaced 18.8 lb/sls of H20. Cement returns 18 bbls, 83.5 sks. Floats held. Bumped plug at 07:00 a.m. on 9/12/97 with 400 psi. 9/14/97 Ran 77 joints 7', 23# K-55, ST & C, 8rd, casing, landed @ 3501'. Cement with 490 sks of 65/35 POZ, Class B w/8% Gel, 2% CaCl .25#/sk Cello Flake, 6.25#/sk Gilsonite. Followed by 115 sks of Class: B w/2% CaCl2. 25#/sk Cello Flake. Displaced with 137 bbit of H20, 36 cement returns 36bbls, 95.7 sxs., with muddy returns. Floats held. Plug didn't bump. Floats held w/ 1000 PSI final lift. Displace ½ bbl over displacement. 9/23/97 Ran 32 joints 4-1/2', 11.60#, K-55, 8rd LT&C casing. Ran 150 joints 4-1/2' 10.50#, K-55, 8rd ST&C casing. Landed at 7716'. Cement with 525 sks of 50/50 POZ Class B w/4% Gel, 2% KCL, 30.9% FL-52, 300% CD-32. 6.25lb/sk Gilsonite, .25lb/sk Cello Flake. Followed by 105 sks of Class H w/ 750% FL-62, 250% SM, 200% CD-32. Displaced with 121.5 bbls of water with partial returns. No cement returns. Floats held. Check floats w/ 1400 PSI, floats held. Plug didn't bump on 09/23/97. 9/23/97 ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMC. 14. Thereby certify that the foregoing is true and correct DEBRA BIEMENDERFER DATE D	OUL (d(0) A) Altering Casing	Conversion to Injection	
3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markens and zones pertinent to this work.) 9/12/97 Spudded well. Drilled surface hole. Ran 5 joints 9-5/8°, 36#, 8rd ST 8. C, K-55 casing. Landed at 285°. Cement with 280 sks. Clas B cement with 3% Cacl2 and .25 lb/sk Cello Flake. Displaced 18.8 bbls of H20. Cement returns 18 bbls, 83.5 sks. Floats held. Bumped plug at 07:00 a.m. on 9/12/97 with 400 pst. 9/14/97 Ran 77 joints 7°, 23# K-55, ST & C, 8rd, casing, landed @ 3501°. Cement with 490 sks of 65/35 POZ, Class B w/ 8% Gel, 2% CaC .25#/sk Cello Flake, 6.25#/sk Gilsonite. Followed by 115 sks of Class: B w/ 2% CaCl2. 25#/sk Cello Flake. Displaced with 137 bbl of H20, 36 cement returns 36bbls, 95.7 sxs., with muddy returns. Floats held. Plug didn't bump. Floats held w/ 1000 PSI final lift. Displace ½ bbl over displacement. 9/23/97 Ran 32 joints 4-1/2°, 11.60#, K-55, 8rd LT&C casing. Ran 150 joints 4-1/2° 10.50#, K-55, 8rd ST&C casing. Landed at 7716′. Cement with 525 sks of 50/50 POZ class B w/ 4% Gel, 2% KCL, 30/3% FL-52, 300% Clo-32, 6.25lb/sk Gilsonite, 25lb/sk Cello Flake. Followed by 105 sks of Class H w/ 750% FL-62, 250% SM, 200% Co-32. Displaced with 121.5 bbls of water with partial returns. No cement returns. Floats held. Check floats w/ 1400 PSI, floats held. Plug didn't bump on 09/23/97. 9/23/97 ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMC. DEBRA EleMENDERFER TITLE AGENT FOR CONOCO INC. DATE 9/26/97 (This space for Federal or State office use) APPROVED BY	Other: spud & cement report	Dispose Water	
3. Describe Proposed or Corripleted Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) 9/12/97 Spudded well. Drilled surface hole. Ran 5 joints 9-5/8*, 36#, 8rd ST & C, K-55 casing. Landed at 285'. Cement with 280 sks. Clas B cement with 3% CaCl2 and .25 lb/sk Cello Flake. Displaced 18.8 lb/s of H20. Cement returns 18 bb/s, 83.5 sks. Floats held. Bumped plug at 07:00 a.m. on 9/12/97 with 400 psi. 9/14/97 Ran 77 joints 7*, 23# K-55, ST & C, 8rd, casing, landed @ 3501'. Cement with 490 sks of 65/35 POZ, Class B w/ 8% Gel, 2% CaC .25#/sk Cello Flake, 6.25#/sk Gilsonite. Followed by 115 sks of Class B w/ 2% CaCl2 .25#/sk Cello Flake. Displaced with 137 bb/s of H2O, 36 cement returns 38bb/s, 95.7 sxs, with muddy returns. Floats held. Plug didn't bump. Floats held w/ 1000 PSI final lift. Displace ½ bb/l over displacement. 9/23/97 Ran 32 joints 4-1/2*, 11.60#, K-55, 8rd LT&C casing. Ran 150 joints 4-1/2* 10.50#, K-55, 8rd ST&C casing. Landed at 7716'. Cement with 525 sks of 50/50 POZ Class B w/ 4% Gel, 2% KCL, 300% FL-52, 300% CD-32, 6.25lb/sk Gilsonite, .25lb/sk Cello Flake. Followed by 105 sks of Class H w/ 750% FL-62, 250% SM, 200% CD-32. Displaced with 121.5 bbls of water with partial returns. No cement returns. Floats held. Check floats w/ 1400 PSI, floats held. Plug didn't bump on 09/23/97. 9/23/97 ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMC. DEBRA EleMENDERFER TITLE AGENT FOR CONOCO INC. DATE DATE DATE Conditions of approval, if any: Conditions of approval, if any:	তποπ ^ο छ	(Note: Report results of multiple completion on Well Completion Recompletion Report and Log Form.)	
9/14/97 Ran 77 joints 7", 23# K-55, ST & C, 8rd, casing, landed @ 3501". Cement with 490 sks of 65/35 POZ, Class B w/ 8% Gel, 2% CaC .25#/sk Cello Flake, 6.25#/sk Gilsonite. Followed by 115 sks of Class: B w/ 2% CaCl2 .25#/sk Cello Flake. Displaced with 137 bble of H2O, 36 cement returns 36bbls, 95.7 sxs, with muddy returns. Floats held. Plug didn't bump. Floats held w/ 1000 PSI final lift. Displace ½ bbl over displacement. 9/23/97 Ran 32 joints 4-1/2", 11.60#, K-55, 8rd LT&C casing. Ran 150 joints 4-1/2" 10.50#, K-55, 8rd ST&C casing. Landed at 7716". Cement with 525 sks of 50/50 POZ Class B w/ 4% Gel, 2% KCL, 300% FL-52, 300% CD-32, 6.25lb/sk Gilsonite, .25lb/sk Cello Flake. Followed by 105 sks of Class H w/ 750% FL-62, 250% SM, 200% CD-32. Displaced with 121.5 bbls of water with partial returns. No cement returns. Floats held. Check floats w/ 1400 PSI, floats held. Plug didn't bump on 09/23/97. 9/23/97 ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMCI. 14. Thereby certify that the foregoing is true and correct DEBRA EIEMENDERFER TITLE AGENT FOR CONOCO INC. DATE 9/26/97 TITLE AGENT FOR CONOCO INC. DATE DATE ACCEPTED FOR RECORD	B cement with 3% CaCl2 and .25 lb/sk Cello Flake. Displaced 18.8 bbls of H20. Ce	g. Landed at 285'. Cement with 280 sks. Class ment returns 18 bbls, 83.5 sks. Floats held.	
Cement with 525 sks of 50/50 POZ Class B w/ 4% Gel, 2% KCL, 300% FL-52, 300% CD-32, 6.25lb/sk Gilsonite, .25lb/sk Cello Flake. Followed by 105 sks of Class H w/ 750% FL-62, 250% SM, 200% CD-32. Displaced with 121.5 bbls of water with partial returns. No cement returns. Floats held. Check floats w/ 1400 PSI, floats held. Plug didn't bump on 09/23/97. 9/23/97 ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMC. 14. I hereby certify that the foregoing is true and correct DEBRA EIEMENDERFER TITLE AGENT FOR CONOCO INC. DATE 9/26/97 (This space for Federal or State office use) APPROVED BY	9/14/97 Ran 77 joints 7", 23# K-55, ST & C, 8rd, casing, landed @ 3501'. Cement with 490 sks of 65/35 POZ, Class B w/ 8% Gel, 2% CaCl2 .25#/sk Cello Flake, 6.25#/sk Gilsonite. Followed by 115 sks of Class B w/ 2% CaCl2 .25#/sk Cello Flake. Displaced with 137 bbls of H2C, 36 cement returns 36bbls, 95.7 sxs, with muddy returns. Floats held. Plug didn't bump. Floats held w/ 1000 PSI final lift.		
14. I hereby certify that the foregoing is true and correct DEBRA EIEMENDERFER TITLE AGENT FOR CONOCO INC. DATE 9/26/97 (This space for Federal or State office use) APPROVED BY	Cement with 525 sks of 50/50 POZ Class B w/ 4% Gel, 2% KCL, 300% FL-52, 300% CD-32, 6.25lb/sk Gilsonite, .25lb/sk Cello Flake Followed by 105 sks of Class H w/ 750% FL-62, 250% SM, 2()0% CD-32. Displaced with 121.5 bbls of water with partial		
TITLE AGENT FOR CONOCO INC. DATE 9/26/97 (This space for Federal or Spate office use) APPROVED BY	9/23/97 ND, BOP, set sups w/ 62k, make rough cut, install hole cover. RDMCi.		
SIGNED COMMANDAL TITLE AGENT FOR CONOCO INC. DATE 9/26/97 (This space for Federal or State office use) APPROVED BY	14. I hereby certify that the foregoing is true and correct		
(This space for Federal or State office use) APPROVED BY	11 / 1/2 / De mand de l'es		
APPROVED BY TITLE DATE Conditions of approval, if any: ACCEPTED FOR RECORD	SIGNED WINDLESS TITLE AGENT FOR CONOCO I	NC. DATE 9/26/97	
Conditions of approval, if any: ACCEPTED FOR RECORD	(This space for Federal or State office use)		
Conditions of approval, if any: ACCEPTED FOR RECORD	APPROVED BY TITLE	DATE	
	Conditions of approval, if any:		

* See Instruction on Reverse Side

FARMINGTON DISTRICT OFFICE
BY