




Key Four Corners, Inc.

P. O. Box 900, 5651 US Hwy. 64 • Farmington, New Mexico 87499
(505) 327-4935 • (505) 327-0416

DATE: 5-25-98

RIG # 42

RECEIVED
MAY 28 1998

OIL CON. DIV.
DIST. 3

CONOCO INC.
10 DESTA DRIVE, SUITE 100W
MIDLAND, TX. 79705


THIS LETTER IS TO CERTIFY THAT BIG A WELL SERVICE DID RUN DEVIATION SURVEYS AT THE LISTED DEPTH ON YOUR SAN JUAN 28-7 UNIT # 215M WELL, IN SECTION 4, T-27-N, R-7-W, IN RIO ARRIBA COUNTY, NEW MEXICO.

DEPTH	DEGREE DEVIATION	DEPTH	DEGREE DEVIATION
251	1/2	4441	1/2
664	1	4847	3/4
1166	3/4	5253	3/4
1528	1	5656	3/4
1904	1	6066	3/4
2403	1-1/4	6502	1-1/2
2888	3/4	6919	1-1/4
3259	1-1/2	7321	1-1/2
3559	1-1/2	7742	1-1/2
4034	1/2		

TO THE BEST OF MY KNOWLEDGE, I SWEAR THIS INFORMATION TO BE TRUE.

SINCERELY,


JOHN K. RICHARDSON
DRILLING MANAGER


Notary Public

My commission expires: 5/14/99



Division of Key Energy Group, Inc.