



P. O. Box 900, 5651 US Hwy. 64 • Farmington, New Mexico 87499
(505) 327-4935 • 24 Hour Dispatch (505) 325-6892 • (505) 327-0416

DATE: 6-4-98

RIG # 42

RECEIVED
JUL 2 1998

OIL CON. DIV.
DIST. 3

CONOCO INC.
10 DESTA DRIVE, SUITE 100W
MIDLAND, TX. 79705

THIS LETTER IS TO CERTIFY THAT BIG A WELL SERVICE DID RUN DEVIATION SURVEYS
AT THE LISTED DEPTH ON YOUR SAN JUAN 28-7 UNIT # 156M WELL, IN SECTION 7, T-27-N,
R-7W, IN RIO ARriba COUNTY, NEW MEXICO.

E-10-27N-7W

DEPTH	DEGREE DEVIATION	DEPTH	DEGREE DEVIATION
252	1-1/4	4289	3/4
695	1	4788	3/4
1156	1-3/4	5264	1
1556	1-1/4	5726	3/4
1987	1	6161	3/4
2356	1	6569	3/4
2755	1	7040	1-1/4
3167	1	7361	2
3453	1	7637	1-3/4
3849	3/4		

TO THE BEST OF MY KNOWLEDGE, I SWEAR THIS INFORMATION TO BE TRUE.

SINCERELY,

JOHN K. RICHARDSON
DRILLING MANAGER

Notary Public

My commission expires: 6/9/00