

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Phillips Petroleum Company, 1200 Denver Club Bldg, Denver 2, Colorado
(Address)

LEASE Hospah "A" WELL NO. 2 UNIT N S 36 T 26N R 13W

DATE WORK PERFORMED 5-16-56 POOL Bisti

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

TD 5050. Ran 5½" 14# J-55 SS casing (5011.83' less threads), set at 5027.53'.
Cemented with 200 sacks regular cement. Pumped plug to 4995. Tested with 500#
for 30 minutes, held OK.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given
above is true and complete to the best of
my knowledge.

Name _____

Name W. M. Shulz

Title _____

Position Division Superintendent

Date _____

Company Phillips Petroleum Company



OIL CONSERVATION COMMISSION
 ACCIDENT REPORT SLIP
 No. 3
 1
 2