

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

British-American Oil Producing Company
P.O. Drawer 330
Farmington, New Mexico

We are requesting that Oil Commission "Casing Failure Report" forms be filed in triplicate on all wells on which casing failures have occurred. This form should be filed subsequent to repair. You are also reminded that Commission Form C-102 should be filed prior to institution of remedial action on any well on which casing failure has occurred.

British American #2-B Balge, 33-26N-13W

Yours very truly

cc: Oil Conservation Commission
Santa Fe, N.M.

