

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

Land Office Santa Fe
Lease No. 14-08-0001-1400
Unit East Santa Fe Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. 7 is located 1900 ft. from 134 line and 640 ft. from E line of sec. 36
26N 17E 11N
(Twp.) (Range) (Meridian)
Plati Collup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6207 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11-14-62. Rigged up and pulled rods and tubing. Rigged up Halliburton and treated down 3 1/2" casing. Loaded hole and broke down with 153 barrels oil, 1000 psi, at 34 BPM. Treated with 1500/ 20-40 sand, 1000/ 20-40 sand, 1000/ 20-40 sand, 1200 psi at 33 BPM. Flushed with 145 PG, 1400 psi at 30 BPM. Instant shut in pressure 1000 psi, on vacuum in 5 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company
Address P. O. Drawer 330
Farmington, New Mexico

By H. R. L. L. L.
Title Field Superintendent