



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

July 21, 1992

John Alexander
Dugan Production Corp.
P.O. Box 420
Farmington, NM 87499

RE: Mechanical Integrity Test (MIT)
West Bisti Unit #153, K-35-26N-13W

Dear John:

This letter is to confirm our conversation of June 22, 1992. You indicated that the casing-tubing annulus in this well was tested by the BLM for Mechanical Integrity in April 1991. A BLM notice has verified this test. This well no longer requires P&A or TA approval as stated in a letter from this office dated June 15, 1992.

The New Mexico Oil Conservation Division, as a part of its Underground Injection Control authority, requires Dugan Production to perform an MIT on the above injection well once every five years. An MIT will be due April 1996.

If you have any questions please feel free to contact this office.

Sincerely,

Dianna K. Fairhurst

Dianna K. Fairhurst
Deputy Oil & Gas Inspector

DKF/sh

XC: David Catanach-UIC Director
UIC File
DKF File
TA File
Well File