NEW MEXICO OIL CONSERVATION COMMISSION MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY The British American Cil Pro (Ad	ducing ldress)	Compet	Ţ,	Bex.	180,	Denver .	- 1, C	olered	.
LEASE WELL NO.		UNIT		s	-33	Т	263	R	194
DATE WORK PERFORMED		P001	L	Bist	l-Gal	ben			
This is a Report of: (Check appropriate	block)	L	_]	Resul	ts of	Test	of Ca	sing	Shut-o
Beginning Drilling Operations		[3		Reme	dial	Work	;		
Plugging		Γ	\neg	Other					
				-				····	
Detailed account of work done, nature an	nd quar	ntity of	fη	ateri	als u	ısed a	and re	sults	obtaine
FILL IN BELOW FOR REMEDIAL WORK Original Well Data: The Elev. 6225 TD 5133 PBD 5100 Thing. Dia Thing Depth Const. Const	Pr Oil Str	od. In	t		0	-	pl Dat		19-57 5132
Open Hole Interval Produc	cing F	ormati	on	(s)	lelln	n Sen	detone		
RESULTS OF WORKOVER:					FOF			FTE	
				ומ	r Or	CE		FIEI	X.
Date of Test					· 		_		
Oil Production, bbls. per day Gas Production, Mcf per day						_			
Water Production, bbls. per day					 -		-		
Gas-Oil Ratio, cu. ft. per bbl.									
Gas Well Potential, Mcf per day									
Witnessed by								···-	
Timessed by						(Com	pany)		
OIL CONSERVATION COMMISSION		reby c		•	hat th	ne inf	ormat	_	
Name Original Signed Emery C. Arnold		knowle			Origi	nal Sig	gned By . Hogai	y :	~ -
Title Supervisor Dist. # 3	Pos	ition	D4	rted a		erint			
Date 90 v 1 7 1958	Con	npany_						7 D	booter- 1
(AC. CO.	3								

DETAILS OF WORK

Ć....

Page Two
Salge "B" #5
C NE NE Section 33-26N-13W
Bisti-Gallup, New Mexico

Pulled rods, pump & 2" KUE tubing and cleaned out to PBD 5100 KB. Loaded hole w/50 BO, set Baker CI Bridge Plug @ 5022 KB.

Rigged up Dowell, broke formation w/120 BO @ 1700 psi. Fractured w/15,000 lbs sand and 15,000 gals oil at 1700 to 1600 psi, 30 nylon balls on formation @ 1800 to 1700 psi. 15,000 lbs sand and 15,000 gals lse crude @ 1700 psi @ 29 BPM. Flushed w/120 BO @ 1800 psi @ 28 BPM. Total load oil used 978 bbls. Cleaned out 13 ft sand and 20 nylon balls. Swabbed 373 BLO in 56 hrs w/605 BLO to recover. Rigged up and drilled bridge plug. Cleaned out sand to FBD. 680 BLO to recover. 2 BUE tubing @ 5032.98 KB. Ran pump and rods and set well on beam. Well produced 132 BLO and 38 BW in 7 days.

Will issue subsequent report when load oil is recovered.

	COMMISSION COMMISSION
No. Conkey	
	The second secon
	The second secon
	The second secon
Property of the same	And the second s
	The state of the s
	and the second