



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 001026-A
Unit Sullivan

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 12, 1956

Well No. J-5 is located 400 ft. from S line and 500 ft. from W line of sec. 20
SW Section 20 20N 13W 10N14
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox Santa Fe New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5240 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11-10-56, Total Depth 5100'.
Ran 157 joints of 1 1/2", 19.50#, J-55 casing (5097') set at 5107' with 125 sacks regular cement, 125 sacks Pozzalex, 4% Col, followed by 50 sacks regular cement.
Held 100% for 30 minutes.
Top of cement of temperature survey at 3720'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations can be commenced.

Company El Paso Natural Gas Company

Address Box 907

Farmington, New Mexico

ORIGINAL SIGNED SAMUEL SCHULEMAN

By _____

Title Petroleum Engineer

