

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 978091  
Unit Gov. Dearthit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Set Surface Casing</u>	<u>XX</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 23, 1957

Dearthit  
Well No. B-13 is located 660 ft. from SK line and 1900 ft. from E line of sec. 26  
C - SW, SE Section 26 26N 13W New Mexico P.M.  
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Histi-Gallup San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

ground level  
The elevation of the ~~bottom floor~~ above sea level is 6273 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 1 3/4" hole to 215' EB. Ran 5 joints 9-5/8" Armo Casing. Landed at 214' EB and cemented with 200 sac Regular Cement. Displaced cement to 194' EB with good returns to surface. Waited 24 hours, then tested. Cement hold OK.




I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company

Address Box 180  
Denver 1,  
Colorado

Original Signed By J. E. Stein  
By \_\_\_\_\_  
Title District Engineer



1950 FEB 27  
1950