


Indian Agency Window Rock
Re-cess
Allottee 14-20-601-778
Lease No. _____



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
JUN 5 1956

Well No. 1 is located 1550 ft. from N line and 990 ft. from S line and 25 sec. 25
NW 1/4 Sec. 25 25N 9W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Ballard Mt. San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6306 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-12-56 TD 95' N.M. Set 3 joints 86' of 8-5/8" CD 24# J-55 casing at 95' with 70 sacks cement, circulated.

5-17-56 Pressured up on casing to 5000'. No pressure decrease in 35 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company HENDERSON-MONTEN
Address 403 1/2 West Broadway
Farmington, New Mexico

By [Signature]
Title Field Superintendent

RECORD

10/10/10

10/10/10