

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078091
Unit Gov. Dearthit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Set Surface Casing</u> XX

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 6, 19 57

Dearthit

Well No. B-14 is located 1980 ft. from Box line and 1980 ft. from Box line of sec. 28

C-NE, SW, Section 28
(1/4 Sec. and 1/4 Sec. No.)

26N
(Twp.)

13W
(Range)

New Mexico P.M.
(Meridian)

Bisti-Gallup
(Field)

San Juan

(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the ground level ~~datum~~ above sea level is 6299 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 1 3/4" hole to 215' KB. Ran 5 joints 9-5/8" Armaco Casing. Landed at 214' KB and cemented with 200 sack regular cement. Displaced cement to 194' KB with good returns to surface. Waited 24 hours, then tested. Cement held OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE BRITISH-AMERICAN OIL PRODUCING COMPANY

Address BOX 180

DENVER 1

COLORADO

Original Signed By
Thomas M. Hogan

By

Title District Superintendent

1000

1000

1000