

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **074091**
Unit **Gov't. Benthit**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Set Surface Casing	XX

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 10, 19 **57**

Benthit

Well No. **B-11** is located **840** ft. from **(N)** line and **975** ft. from **(E)** line of sec. **29**

6-NE, NE Section 29
(1/4 Sec. and Sec. No.)

26N

13W

New Mexico P.M.

Bisti-Gallup
(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

ground level

The elevation of the ~~drill hole~~ above sea level is **6345** ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 13-3/4" hole to 215' KB. Ran 5 joints 9-5/8" Armo Casing. Landed at 214' KB and cemented with 200 sac Regular Cement. Displaced cement to 194' KB with good returns to surface. Waited 24 hours, then tested. Cement held OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The British-American Oil Producing Company**
Address **Box 180**
Deliver 1
Colorado
Original Signed By: **Thomas M. Hogan**
By _____
Title **District Superintendent**



RECEIVED
SEP 10 1900