

Form 3160-5
(November 1983)
(Formerly 9-331)

5 BLM

1 File

1 - WBU wios

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF-078091

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT ASSIGNMENT NAME

West Bisti Unit

8. FARM OR LEASE NAME

West Bisti Unit

9. WELL NO.

121

10. FIELD AND POOL, OR WILDCAT

Bisti Lower Gallup

11. SEC. T., R., W., OR BLK. AND

Sec. 29, T26N, R13W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

P.O. Box 420, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL & 1980' FWL

14. PERMIT NO.
API# 30-045-05714-0000

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Shut-in Extension

PCLL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Request 1 year extension of shut-in status of this well to continue evaluation of entire unit. Casing will be pressure tested to insure integrity. If casing fails pressure test, plans will be presented immediately to repair casing or plug and abandon.

THIS APPROVAL EXPIRES DEC 31 1991

RECEIVED

JAN 28 1991

OIL CON. DIV.
DUGAN

APPROVED

John Alexander
AREA MANAGER

18. I hereby certify that the foregoing is true and correct

SIGNED John Alexander

TITLE Petroleum Engineer

DATE 12-12-90

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NWCC