



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. E.M. 013192  
Unit A. L. Duff

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<b>I</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 26, 1956

Well No. A. L. Duff  
1 is located 640 ft. from EN line and 1900 ft. from E line of sec. 19

35/4 Section 19  
( $\frac{1}{4}$  Sec. and Sec. No.)

28N  
(Twp.)

13W  
(Range)

E.M.P.M.  
(Meridian)

Kildont  
(Field)

Santa Juan  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cut off 5-1/2" casing at 393'. Pumped cement through 5-1/2" casing and set cement plug from 293' to 393'. Pelled 5-1/2" casing & set 25' cement plug in top of surface casing.

Set 4-1/2" CD pipe 4' above ground level for permanent marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may commence.

Company Shelly Oil Company

Address Box 436

Farmington, New Mexico

By

Title District Foreman

