

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

| Budget | Bureau | No. | 42-R358.4 |
|--------|---------|-------|-----------|
| Anning | alernin | × 19- | -31-60 |

GPO 918507

Land Office Santa Pe

Lease No. N. N. 013492

Unit As L. Daff

SUNDRY NOTICES AND REPORTS ON WELLS

| | X | SUBSEQUENT REPORT | OF WATER SHUT-OFF | |
|--|--|--|--|--|
| NOTICE OF INTENTION TO CHANGE PLANS | | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | | |
| NOTICE OF INTENTION TO TEST WATER SHU | | | OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR RE | PAIR WELL | SUBSEQUENT REPORT | OF RE-DRILLING OR | REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDI | ZE | SUBSEQUENT REPORT | OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER | CASING | SUPPLEMENTARY WE | L HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | | | |
| (INDICATE ABO | VE BY CHECK MARK NATU | RE OF REPORT, NOTIC | E, OR OTHER DATA) | |
| | | | Sept | ember 11., 19 |
| A. L. Daff ell No. 3is located 19 | 280ft. from{S | line and 198 | ft. from [E] | line of sec. |
| 1/4-9E/4 | 26N 13 | , | Meridian) | |
| (1/2 Sec. and Sec. No.) | (Twp.) (Rang | | Meridian) | |
| designated (Gallup) | County or Sub | division) | (State or 7 | Cerritory) |
| (Field) Best UH | , (_ouns) or but | | (Diano of 1 | |
| e elevation of the derrick floor | r above sea level i | s ft. | in the second se | en e |
| | DETAILS | OF WORK | | |
| ate names of and expected depths to object i | tive sands; show sizes, we ng points, and all other i | ights, and lengths of proposed w | proposed casings; indicork) | cate mudding jobs, cer |
| It is our intention drill of 5200' to test the Gell as follows: 250' of 10-3/4" OD easi: | lup formation. ng, 32.75# EW 1 | Our essing | program is | |
| stoks coment. Circulate | | | | |
| sucks coment. Circulate 5200° of 5-1/2" OD casing | g, 14# 58 J- 55 | , comented w | th 250 | |
| sucks coment. Circulate 5200' of 5-1/2" OD casing sacks coment. | | | 9 | |
| staks coment. Circulate 1200' of 5-1/2" OD casing acks coment. | receive approval in writi | | 9 | na may be company |
| Stake coment. Circulate 5200 of 5-1/2" (B) casing acks coment. I understand that this plan of work must | receive approval in writi | | 9 | na mayby comp |
| Stake coment. Circulate 5200° of 5-1/2° OD casing sacks coment. I understand that this plan of work must company SKELLY OIL COMPANY Box 426 | receive approval in writi | | 9 | na match com. |
| Staks coment. Circulate 5200° of 5-1/2° OD casing sacks coment. I understand that this plan of work must company SKELLY OIL COMPANY Box 426 | receive approval in writi | ng by the Geological S | 9 | |
| 5200° of 5-1/2° OD casing sacks commt. I understand that this plan of work must ompany SKELLY OIL COMPANY | receive approval in writi | ng by the Geological S | Curvey before operation | B. Coaper |

NEW MEXICO OIL CONSERVATION COMMISSION

Well Location and Acreage Dedication Plat

| tion A. | | | Date September 10, 1957 |
|---------------------------------|---|--|--|
| rator SKELLY OIL | COMPANY | .ease A. L. DUFF | |
| l No. <u> </u> | tter J Section 20 | Townshi | p 26 NORTH Range 13 WEST, NM |
| ntv SAN JUAN | G. L. Elevation | , 1980 F | eet From the KAST Lin |
| of Producing Forma | ation Caller | Pool # | ted Acreage 40 Acre |
| Is the Operator the | only owner* in the d | ledicated acreage | ndesignated on the plat below? |
| Yes x No | • | | |
| consolidated by com | estion one is "no," h | ave the interests | of all the owners been |
| "yes," Type of Cons | solidation | or otherwise? | Yes No . If answer is |
| If the answer to qu | estion two is "no," l | ist all the owner | s and their respective interest |
| below: | | | |
| Owner | | tand Da | |
| <u>Owner</u> | | Land De | scription |
| | | | |
| | | | |
| | | | |
| | | | 11.8 (4.1) |
| ion.B | ······································ | | |
| ; | | 1 1 | |
| l 1 | | 1 | This is to certify that the |
| <u> </u> | | A STATE OF THE PARTY OF THE PAR | information in Section A |
| į | قع ا | 5 | above is true and complete |
| <u>;</u> | | | to the best of my knowledge |
| 1 | 4 | | and belief. |
| | ++3 | 9 | SKELLY OIL COMPANY |
| 1 | | 4 8 60 | (Operator) |
| | | WO | (Signed) P. E. Cosper |
| İ | | | (Representative) |
| | | | |
| 1 | | | Box 426, Farmington, New Mex Address |
| | 20 | | |
| | | | |
| , | | | This is to certify that the |
| i , | 0 | <u> </u> | well location shown on the plat in Section B was plotte |
| | | | from field notes of actual |
| | | | surveys made by me or under |
| , | I | | my supervision and that the |
| | | | same is true and correct to |
| | \ | i I | the best of my knowledge and |
| l I | |] | belief. |
| | <i>2</i> , | | Date Surveyed 8 SEPTEMBER 19 |
| | | ! | A Chan |
| | | 1 | Registered Professional |
| i | | J | |
| | | | Engineer and/or Land Surveyo |
| 10 660 990 1320 1650 1 9 | 80 2310 2640 2000 1 | 500 1000 500 | Engineer and/or Land Surveyor James P. Leese |