(Feb. 1961)					

M, 4 Jec. 20

(1/4 Sec. and Sec. No.)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Offic	. Sev M	wicu.
Lease No.	<u> </u>	
Unit	Huerfano	Unit

New Mexica

AT II

PECANED

SUNDRY NOTICES AND REPORTS ON WELL &UG 2 7 1959

NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT	A STAP ANT
(INDICATE ABOVE BY CHECK MAR	RK NATURE OF REPORT, NOTICE, OR OTHER DATA)	

N.M.P.M.

(Meridian)

The elevation of the derrick floor above sea level is 6446 ft.

DETAILS OF WORK

(Range)

Wildcat Gallup & Daketes San Juan Rew Mexico (Field) (County or Subdivision) (State or Territory)

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-22-59 Total Lepth 6776'. Temporary bridge plug at 6300'. oil fractured Callup perf. interva.s 5790-5807; 5835-5843; 5882-94 w/2 bJ/ft. w/27,000 gallons oil and 30,000% sand. BD pr. 2200%, max. pr. 3800%, avg. tr. pr. 2900-3200-3500%. I.R. 34.6 BFM. Flush 11,640 gallons.

2-22-59 Temporary bridge plug at 5760'. Gil fractured Gallup perf. intervals 5603-5613; 5622-5629; 5718-5727 v/2 DJ/ft. v/26,411 gallons oil and 30,000/ sand. BD pr. 2000%, max. pr. 3500%, myg. tr. pr. 2900-3300%. I.R. 54.2 BFM. Flush 11,020 gellons.

I unders	and that this plan of work must receive approval in writing k	RELLIVED
I understand that this plan of work must receive approval in writing by the Geological Surv Company Il Paso Natural Gas Company		
Address	Box 997	OIL CON, COM. DIST. 3
	Farmington, New Mexico	By ORIGINAL SIGNED J.J. TILLERSON
***************		Title

