

			X

1-40

(SUBMIT IN TRIPLICATE)

1-8100

UNITED STATES

1-0

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

1-2

Indian Agency _____

Allottee **14-20-603**

Lease No. 1444

Harker Nava'jo

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<div style="text-align: center;"> RECEIVED JUN 28 </div>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

June 27 19 **61**

Well No. #1 is located 790 ft. from [N] line and 990 ft. from [E] line of sec. 23

NE/4 NE/4 Sec. 23

(1/4 Sec. and Sec. No.)

26N

(Twp.)

11W

(Range)

Abstract

(Meridian)

Basin Dakota

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)


The elevation of the derrick floor above sea level is 6332 ft. **G.L.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spurred 4:15 P.M. 6/24/61

Set 7 jts. 10 3/4" 32.50# casing @ 210'KB w/150 ex cement 2% HA-5. Plug down @ 12:35 AM 6/25/61. WOC 8 hrs. test csg. w/750# for 30 min. OK. Drilling.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southwest Production Company

Address 162 Petr. Center Bldg.,

Farmington, N. H.

Original signed by
Carl W. Smith

By

Title Production Sept.