



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. KN 013492  
Unit A. L. Duff

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	RECEIVED	SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>Surface</u>	<u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS	JUL 3 1958	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	U.S. GEOLOGICAL SURVEY	SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	FARMINGTON, NEW MEXICO	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL				

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 1, 1958

A. L. Duff  
Well No. 12 is located 660 ft. from S line and 660 ft. from E line of sec. 18  
S/2-S2/4 Section 18 24N 13W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
McCl (Gallup) Bld. San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6319 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**WORK:** 1:00 P.M., 6/17/58.

Run & set 10-3/4" casing at 217' & cemented with 225 sacks reg. cement, 2% CaCl.  
Cement circulated to surface.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY  
Box 426  
Address Farmington, New Mexico

By (Signed) E. E. Cosper  
Title District Superintendent