


NEW MEXICO OIL CONSERVATION COMMISSION
NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

REV. 11-1-64

Operator El Paso Natural Gas Company		Well Name and Number Thornton Unit #104 (20)	
Location of Well Unit 3 Sec. 27 Twp. 36S Rge. 10E		Annul - (Give Year) 1972	Initial - (Give Date)
UPPER COMPLETION	Reservoir or Pool (17)	☐ GAS ☐ OIL	☐ FLOWING ☐ ARTIFICIAL LIFT
LOWER COMPLETION	Reservoir or Pool (18)	☐ GAS ☐ OIL	☐ FLOWING ☐ ARTIFICIAL LIFT
		☐ NEW ☐ OWO	☐ TUBING ☐ TUBING

Date	Lower Zone		Upper Zone	
	Shut-in		Flow Test	
	Casing	Tubing	Csg	thb
8/7/72		620	172	434
8/8/72		631	206	485
8/9/72		641	215	436
8/9/72		651		143
8/10/72		661		139

Remarks:



The results of this test indicate (No Packer Leakage) (Packer Leakage) in this well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

AUG 25 1972

APPROVED _____ 19____
NEW MEXICO OIL CONSERVATION COMMISSION


BY Al R. Kendrick

PETROLEUM ENGINEER DIST. NO. 3

OPERATOR El Paso Natural Gas Company

BY [Signature]
TITLE Field Test Engineer

DATE _____



E P N G
Annual Packer Leakage Test
1972

HUDEPANO UNIT #104 (GP)
Unit P Sec. 17-28-10
San Juan Co., New Mexico

• GL Zone • DK Zone