

well file

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS ROAD - AZTEC

87410

March 14, 1974

I. R. TRUJILLO

CHAIRMAN

LAND COMMISSIONER

ALEX J. ARMIJO

MEMBER

STATE GEOLOGIST

A. L. PORTER, JR.

SECRETARY - DIRECTOR

Mr. Larry Van Ryan
El Paso Natural Gas Co.
P. O. Box 990
Farmington, New Mexico

Re: Huerfano Unit #104, P-17-26N-10W
Michener A #4, H-28-28N-9W
Rincon Unit #127, A-28-27N-6W
San Juan 28-7 Unit #109, A-18-27N-7W

Dear Mr. Van Ryan:

The attached copy of the 1973 Annual Packer-Leakage Test Report for each subject well indicates communication between the producing zones.

You are hereby directed to take immediate action to casue the zones to be separated as required by Rule 112-A and the order which authorized each multiple completion.

If there are questions, please contact us.

Yours very truly,



A. R. Kendrick
Engineer, District #3

ARK:mc

cc: Oil Conservation Commission
P. O. Box 2088
Santa Fe, New Mexico

NEW MEXICO OIL CONSERVATION COMMISSION
NORTHWEST NEW MEXICO PACER-LEAKAGE TEST

Operator EL PASO NATURAL GAS COMPANY		Well Name and Number Huerfano Unit #104	
Location of Well Unit P Sec. 17 Twp. 26 Rge. 10		TYPE OF TEST → 1973	Annual - (Give Year) 1973
UPPER COMPLETION	Reservoir or Pool GL	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT
LOWER COMPLETION	Reservoir or Pool DK	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT
		☐ NEW ☐ OWWO	☐ CASING ☒ TUBING
		☐ CASING ☒ TUBING	☐ CASING ☒ TUBING

Date	Lower Zone	Upper Zone	
	Shut-in	Flow Test	
	Tubing	Casing	Tubing
11-26	247	437	407
11-27	255	437	415
11-28	270	437	415
11-29	207		
11-29	207		

REMARKS:



The results of this test indicate (No Packer Leakage) (Packer Leakage) in this well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Operator notified to repair
3-14-1974
APPROVED _____
NEW MEXICO OIL CONSERVATION COMMISSION

OPERATOR EL PASO NATURAL GAS COMPANY
BY William D. Welch
TITLE Well Test Engineer
DATE 2-28-74

DAYS

1 2 3 4 5

PRESSURE

Psig
 700

Both Zones
 Shut In

DK.

Flowing

E P N G
 Annual Packer Leakage Test
 1973

HUIERFANO UNIT #104 (GD)
 Unit P Sec. 17-26-10
 San Juan Co., New Mexico

• GL Zone
 o DK Zone

