

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Federal <input type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Ka-Des-Pah
3. Address of Operator PO Box 990, Farmington, NM 87401	9. Well No. 1 (P&A)
4. Location of Well UNIT LETTER K 1528 FEET FROM THE South LINE AND 1906 FEET FROM THE West LINE, SECTION 18 TOWNSHIP 26N RANGE 8W NMPM.	10. Field and Pool, or Wildcat Ballard Pictured Cliffs
15. Elevation (Show whether DF, RT, GR, etc.) 6205'GL	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Due to non-commercial production this well has been plugged and abandoned in the following manner:

on 10-21-71: Spotted a 30 sack cement plug below the packer set at 1892', spotted 10 sack cement plug on top of packer. Perforated squeeze holes (4) at 1245'. Squeezed 25 sacks cement thru perfs, left 25 sacks cement inside 5 1/2" casing at 1245'. Bradenhead squeezed 75 sacks cement down 5 1/2" X 8 5/8" annulus.

On 10-22-71, placed a 10 sack cement plug at the surface with a 4' x 4" Plug and Abandoned marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed F. H. WOOD TITLE Petroleum Engineer DATE November 12, 1971

APPROVED BY *Emory C. Cunniff* TITLE SUPERVISOR DIST. #3 DATE NOV 12 1971

CONDITIONS OF APPROVAL, IF ANY: