

(SUBMIT IN TRIPLICATE)

UNITED STATES

Land Office **SF**  
Lease No. **079679**  
Unit **Dahl-Taylor**

**ILLEGIBLE**

**SUNDR. NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	<b>X</b>
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**April 15**, 19 **58**


Well No. **1** is located **1792** ft. from **N** line and **1750** ft. from **W** line of sec. **17**  
**NE SW/4 Section 17** (1/4 Sec. and Sec. No.)  
**Undesignated** (Field)  
**26-N** (Twp.) **11-W** (Range) **NMPM** (Meridian)  
**San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **6161** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**4-8-58 Repotential Test. The production for the first 24 hours was 125 barrels of fluid of which 100% was oil. Gravity, ° API - 40.2**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Products Company**

Address **Post Office Box 1561**  
**Farmington, New Mexico**

**ORIGINAL SIGNED BY: JOSEPH E. KREGER**

By **Petroleum Engineer**