



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency \_\_\_\_\_  
Allettee Window Rock  
Lease No. 24-00-402-735

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 98 is located 2040 ft. from S line and 640 ft. from E line of sec. 23  
6 NE SE 23 20 24N 10W  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Black Gulch San Juan New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6432 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

20 2145 LB - 2100 2142 LB - Packed rods, pump and tubing. Cleaned out with sand pump to 2142 LB. Run 2-1/2" x 2" NPS Lane Wells 2100-2142 on 240 joints 2" NPS 2142, 2-25 Sals tubing. Electric line. (2142-2142) landed at 2142-2142. Set pump with 20,000 LB. tension, set slips and pulled off hook. Hooked up wellhead and then into injection system.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing Company  
 Address P. O. Box 120  
Farmington, New Mexico  
 Original Signed By: Nae R. Stone  
 By \_\_\_\_\_  
 Title Field Superintendent