



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Window Rock
Allottee _____
Lease No. **14-22-403-739**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Report of running surface log XI

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 5, 1956

NAVAJO
Well No. **1** is located **260** ft. from **[N]** line and **640** ft. from **[W]** line of sec. **15**
NW, NW, Sec 15 **26 N** **14 W** **100M**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 9" hole and reamed to 15" hole to 1013' KB. Ran 10-3/4" 32.75' 2-40 Casing equipped with Baker Centralizers and Guide Shoe landed at 1002' KB and cemented with 500 SUX 25 Gel Cement. Pumped plug to 963' KB with good returns to surface. Waited 24 hours, drilled out under surface casing and tested with 900 PSI for 10 minutes. Held OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The British-American Oil Refining Company**

Address **Box 100**
Denver 1, Colorado

Original Signed by:
By **Thomas M. Hogan**

Title **District Superintendent**

