

(SUBMIT IN TRIPLICATE)

Indian Agency **Window Rock, Ariz.**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **11-20-603-2070**
Lease No. _____

		11		

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

JAN 13 1958

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 9, 1958

Consolidated
Well No. **1 Navajo** is located **660** ft. from **1/4 S** line and **660** ft. from **1/4 W** line of sec. **11**
SW/4 Sec. 11 **T26N** **R17W** **10TH**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Window **San Juan County** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5473** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The well was plugged as follows:

	From - To	Feet	Seals
Morrison-Sabota	4838-4400	438	125
Gallup	3650-3500	150	125
Base Masoverde	2750-2600	150	125
Top "	550-400	150	125
Surface pipe Base	180-110	70	125
" " Top	17- 0	17	125



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **DAVIS OIL COMPANY**

Address **802 Midland Savings Bldg.**
Denver, Colorado

By **Craig C. Ramsey**
Title **Asst. Division Geologist**

