

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Navajo Tribal
Allottee _____
Lease No. 14-20-603-1033

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

RECEIVED
JUN 12 1963
U. S. GEOLOGICAL SURVEY
CARMEL, CALIF. NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Navajo Tribal "P" Farmington, New Mexico June 12, 1963

Well No. 1 is located 790 ft. from S line and 790 ft. from W line of Sec. 8
SW/4 SW/4 Section 8 T-36N R-15W N.M.P.M.
(34 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 9220 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As a result of not obtaining commercial shows of oil or gas, we propose to plug and abandon the Navajo Tribal "P" No. 1 as follows:

1. Spot 40 sacks from 7050 to 7145 (Top of Cambrian 7130).
2. Spot 40 sacks from 6750 to 6860 (Top of Devonian 6783).
3. Spot 40 sacks from 6550 to 6650 (Top of Mississippian 6603).
4. Spot 60 sacks from 6300 to 6450 (Top of Lower Permian 6351).
5. Spot 40 sacks from 4935 to 5035 (Top of Pennsylvanian 4985).
6. Spot 40 sacks from 3700 to 3800 (Top of DeChelly 3765).
7. Spot 60 sacks from 2000 to 2150 (Top of Entrada 2090 and Todilte).
8. Spot 40 sacks from 1480 to 1580 (Bottom of surface casing at 1527).
9. Spot 10 sacks surface to 30' and erect abandonment marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address P. O. Box 480

Farmington, New Mexico

ORIGINAL SIGNED BY
F. H. HOLLINGSWORTH

By _____

Attn: L. O. Spear, Jr.

Title Petroleum Engineer

Verbally approved 6/10/63 McGrath to Hollingsworth.