



RECEIVED (SUBMIT IN TRIPLICATE)

SEP 10 1958

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
DIST. 3Land Office Santa FeLease No. NE 016089Unit W. F. Saunders

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of Setting of Bridge Plug</u>	<u>X</u>
	<u>Report of Perfor. & Squeeze Jobs</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 5, 1958

W. F. Saunders
Well No. 1 is located 440 ft. from S line and 1980 ft. from E line of sec. 11SW 1/4 - SE 1/4 Section 11
(1/4 Sec. and Sec. No.)26N
(Twp.)11W
(Range)N.M.P.M.
(Meridian)Wildcat - Dakota
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 6484 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; include mudding jobs, cementing points, and all other important proposed work)

Run & set Baker model H-32 magnesium bridge plug at 6505' & dumped 1 sk. cement on top of plug, plugging back to 6497'.

Perforated 7" casing 5610-11' w/1/4 Lane Wells Kene shots. Squeezed perf 5610-11' w/100 sks. reg. cement & 100 sks. poxm. BDP 1500#, Max. Squeeze Press. 1500#, Min. Squeeze Press. 600#. Squeezed perfs. 5610-11' w/80 sks. cement, 30% poxm, put 70 sks. in formation, reversed out 10 sks. BDP 1800#, Max. Sq. Press. 4000#.

Perforated 7" casing 5460-61' w/1/4 Lane Wells Kene shots. Squeezed 7" casing perfs. 5460-61' w/100 sks. cement 30% poxm 25 gal. BDP 2200#, Max. Squeeze Press. 2200#, Min. Squeeze Press. 800#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY

Box 426

Address Farmington, New Mexico(Signed) F. E. CooperBy District Superintendent

Title