

APPROVED

OCT 8 1956

(SUBMIT IN TRIPLICATE)

UNITED STATES

JERRY W. LO
ACTING DISTRICT ENGINEER

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency **Navajo Allottee**

Allottee

Lease No. **14-20-603-770**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 20, 1956

Well No. **1** is located **990** ft. from **INT** line and **600** ft. from **W** line of sec. **7**
Section 7 (4 Sec. and Sec. No.)
Ballard (Field)
San Juan (County or Subdivision)
New Mexico (State)
RECEIVED
AUG 24 1956
U. S. GEOLOGICAL SURVEY

The elevation of the derrick floor above sea level is **6190** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date 7-31-56.
 On 7-31-56 Total Depth 130'.
 Run 5 joints 8 5/8", 30#, 114" casing (114") set at 126' with 100 sacks
 regular cement circulated to surface.
 Held 900# for 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**

Address **Box 997**

Farmington, New Mexico

By **[Signature]**
Petroleum Engineer

Title

1000



1000