

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office.....Santa Fe, N. Mex.

Lease No. SF 078388-A

Unit _____

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Sec. 10
T-26-N
R-9-W

A 4x4 grid with a small circle in the bottom-left cell.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 15.....1964

Well No. 5-10 is located 1190 ft. from ~~the~~ S line and 1450 ft. from ~~the~~ W line of sec 10

SW 1/4 of Sec. 10 26 N 9 W NMPM
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Basin Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

APR 21 1964

The elevation of the derrick floor above sea level is ft. Ground Elevation 11326

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-13-64 Ran 209 jts. 6811' of 4-1/2" casing set at 6800' with DV tool at 2155'. Cemented bottom with 240 sacks of class A 50-50 Pozmix with 6% gel, 1/8# of gel flake to sack. Plug down at 8:10 a.m. Opened DV tool and circulated 6 hours. Cemented thru DV tool with 120 sacks of class C cement with 4% gel with 1/3 cubic feet of Strata-Crete and 1/8# of gel flake per sack. Plug down at 2:30 p.m. Rig released at 4:00 p.m. Completion rig will be moved in to drill out cement and test casing at that time.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Austral Oil Company Incorporated

Address300 San Jacinto Bldg.....

Houston, Texas

77002

By R. Copeland
R. Copeland
Title Drilling & Production Supt.