



ILLEGIBLE

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 000364
Unit Nickman

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 14, 1956

Well No. 1-A is located 1650 ft. from S line and 990 ft. from W line of sec. 10

Section 10 26N 12E R4N
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Hildont San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6004 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-10-56. Total Depth 5335'.
Ran 169 joints 5 1/2", 15.50#, J-55 casing (5325') set at 5335' with 150
sacks regular cement, 150 sacks Pozmix, 150# Floccs, 4# Gel.
Held 1000# for 30 minutes.
Top of cement by temperature survey at 4240'.

I understand that this plan of work must receive approval in writing by the Geological Survey before work may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By Verly

Title Regional Geologist



