For (1	m 9 Feb.	-3311 1951)	P	P	RO	VC	ΕD	
				JUL	. 27	1956		
		ACT	JE ING	R R Dis	Y W. TRIC	LONG	DEP.	Į,
		-						

(SUBMIT IN TRIPLICATE)

## UNITED STATES ARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No.	080384
Unit	Hickman

SUNDRY NO	TICES AND	REPOR 7	rs on wells	
NOTICE OF INTENTION TO DRILL	SII	BSFOUENT REPORT	F OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS_			OF SHOOTING OR ACIDIZING	1 1
NOTICE OF INTENTION TO TEST WATER SHU	i (1		OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR RE	1 31		OF RE-DRILLING OR REPAIR	1
NOTICE OF INTENTION TO SHOOT OR ACIDI	ZESU	BSEQUENT REPORT	OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER			LL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL.		andoil Fra	cture	X
<u></u>				
(INDICATE ABO	VE BY CHECK MARK NATURE	OF REPORT, NOTIC	E, OR OTHER DATA)	
			July 10	10 56
	**			, 17
W/ 11 N/	650 (L C 200	. 1000	C. C. Haller	10
Well No. 1-A is located 1	S [S]	line and	$\mathbb{Z}$ line of se	c. <u>40</u>
SW Section 10	6n 12w	nay.		
SW Section 10 2 (% Sec. and Sec. No.)	(Twp.) (Range)	(1	Meridian)	
Wildcat		Juan	New Nexteo	
(Field)	(County or Subdivi	sion)	(State or Territory)	
The elevation of the derrick floor	l	KUSIF (*		
The elevation of the derrick noof	above sea level is	oco- It.		
	DETAILS OF	F WORK		
(State names of and expected depths to object i	ive sands; show sizes, weigh	ts, and lengths of	proposed casings; indicate mudding	y jobs, cement-
				,
5-20-56 T.D. 5335 . Peru				
Sandoil fractured Gallup				
with 48,400 gallons oil a	nd 50,000; send.	Maximum	pressure 2400#, aver	<b>s</b> ee
treating pressure 2300#. Natural sage 1140 MCF/D.	Tulection Late	44.5 Spie.	/min. Flush 5200 ga	LLions.
BEOTEST SPEE TIME SEE IN-				
5-22-56 Total Depth 5335*	. Thamp. R.D. co	t at 50181	. Sandatl fractured	i (tallum
perforeted intervals 4998	-5018 with a sho	te/ft_ wit	h 50.622 aallong of	end
75,000# sand. Maximum per	essure 2750#. av	orace tree	ting pressure 2400#.	Injec-
timm rate 41 bbls./min.	Flush 5000 galle	ns. Matur	al sage 1450 MCF/D.	
· •	•			
I understand that this plan of work must	receive approval in writing b	y the Geological S	ourvey before operations may be cor	mmenced.
Company El Paso Matural	Oss Commony			
Company KI Paso Intural				
Address Box 997				
			FTA	0
Farmington, New	Mexico	Ву	Fw Bogo	
		CD+ 1	Datrolam Burken	
		Title	rem means withings.	