

3004505924

CLIENT: R.C. CLICKBLAGG ENGINEERING, INC.
P.O. BOX 87, BLOOMFIELD, NM 87413
(505) 632-1199LOCATION NO: BR316C.O.C. NO: 6629

FIELD REPORT: CLOSURE VERIFICATION

PAGE No: 1 of 1STATION NAME: NICKSONWELL # 11PIT: NADATE STARTED: 3/25/99QUAD/UNIT: L SEC 11 TWP: 26N RNG: 8W PM: NM CNTY: ST NM

DATE FINISHED: _____

ELEVATION: 2180' FSL / 1190' FWL CONTRACTOR: NAENVIRONMENTAL
SPECIALIST: NVEXCAVATION APPROX. NA FT. x NA FT. x NA FT. DEEP. CUBIC YARDAGE NADISPOSAL FACILITY: ON-SITE REMEDIATION METHOD: CLOSE AS IS.LAND USE: RANGE LEASE: _____ FORMATION: OK

FIELD NOTES & REMARKS:

PIT LOCATED APPROXIMATELY 132 FT. 574E FROM WELLHEADDEPTH TO GROUNDWATER: >100' NEAREST WATER SOURCE >1000' NEAREST SURFACE WATER: >1000'

MOOD PAVING CODE _____ NMCD TPH CLOSURE STD: _____ PPM

CHECK ONE

TANK AND EXCAVATION DESCRIPTION:

**TANK BOTTOM
SUBSURFACE SOIL SAMPLING**☒ PIT ABANDONED☐ STEEL TANK INSTALLED☐ FIBERGLASS TANK INSTALLED

GRAVEL OBSERVED ON GROUND SURFACE WHERE TANK WAS LOCATED, SOIL CONSISTED OF DR. YELL. ORANGE SAND, NON COHESIVE, SLIGHTLY MOIST, FIAM, NO APPARENT DISCOLORATION OR HC ODOOR OBSERVED/DETECTED W/IN ENTIRE BORING, NO APPARENT HC ODOOR DETECTED W/IN OVM SAMPLE.

Tank Pad - for record
not pit

CLOSED

SCALE


0 FT

FIELD 418.1 CALCULATIONS

TIME	SAMPLE I.D.	LAB No:	WEIGHT (g)	mL. FREON	DILUTION	READING	CALC. ppm

PIT PERIMETER

PIT PROFILE

OVM
RESULTS

SAMPLE ID	FIELD HEADSPACE PID (ppm)
1 @	
2 @	
3 @	
4 @	
5 @	

TB @ 4' 0.0

LAB SAMPLES

SAMPLE ID	ANALYSIS	TIME
TB @ 4'	TPH (8015)	1300

PASSED

NOT APPLICABLE

TRAVEL NOTES:

CALLOUT: _____

ONSITE: _____

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Blagg / R.C. Resources	Project #:	403410
Sample ID:	TB @ 4'	Date Reported:	03-26-99
Laboratory Number:	E869	Date Sampled:	03-25-99
Chain of Custody No:	6629	Date Received:	03-26-99
Sample Matrix:	Soil	Date Extracted:	03-26-99
Preservative:	Cool	Date Analyzed:	03-26-99
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **Nickson #11 - Tank Bottom Location.**


Analyst


Review

CHAIN OF CUSTODY RECORD

6624

Client / Project Name				Project Location		ANALYSIS / PARAMETERS										
BLAGG / R.C. RESOURCES				NICKSON WELL SITES												
Sampler: NJV				Client No. 04034-10												
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers						Remarks					
BH-1 @ 6'	3/25/99	1115	E8666	5012	1	✓						ALL SAMPLES PRESERV. - COOL NICKSON #9E - DRIP PIT				
BH-1 @ 6.5'	3/25/99	1135	E8667	5012	1	✓						NICKSON #9E - SEPARABLE PIT				
LF-1	3/25/99	1215	E8668	5012	1	✓						NICKSON #11E - LANDFARM 5 PT. COMPOSITE				
TB @ 4'	3/25/99	1300	E8669	5012	1	✓						NICKSON #11 - TANK BOTTOM LOCATION				
Relinquished by: (Signature) <i>[Signature]</i>				Date 3/26/99 0841		Received by: (Signature) <i>[Signature]</i>		Date 3-26-99 0841								
Relinquished by: (Signature)						Received by: (Signature)										
Relinquished by: (Signature)						Received by: (Signature)										
ENVIROTECH INC. 5796 U.S. Highway 64 Farmington, New Mexico 87401 (505) 632-0615										Sample Receipt						
												Y	N	N/A		
										Received Intact		✓				
										Cool - Ice/Blue Ice		✓				