		UNITED STATE MENT OF THE		SUBMIT IN TRIPLIC	n re _	Form approve Budget Burea	u No. 42-R142
6	_	EOLOGICAL SUF		// verse side)	"	LEASE DESIGNATION	
					- ₀	SF 07894	·
	form for proposi	CES AND REPORTION FOR PERMIT—"	n or plug back	to a different reservoir.		,	
OIL GAR	OTREE				7	UNIT AGREEMENT NA	
NAME OF OPERATOR		 				. FARM OR LEASE NAM	<u> </u>
Bedford, I	nc.					Sullivan	
ADDRESS OF OPERATO	_	0			9	. WELL NO.	
P.O. Box		Farmington,	, New M	Mexico		1E	
mee also space 17 bei	deport location cie ew.)	early and in accordance	with any Sta	to requirements.*	1	O. PIELD AND POOL, OR	WILDCAT
At surface						Gallegos Gallup	
1980 fsl 659 fel Sec. 9 T26NR12W						11. SBC., T., B., M., OR BLK. AND SURVEY OR AREA	
San Ju	an County	, New Mexic				NMPM	N R12W
, PERMIT NO.		15. BLEVATIONS (Show		ca, etc.)	1	2. COUNTY OR PARISH	13. STATE
		6061	<u>DF</u>			San Juan	NM
	Check Ap	propriate Box To In	dicate Nati	re of Notice, Report,	or Oth	er Data	
	NOTICE OF INTENT		1			F REPORT OF:	
TEST WATER SHUT-O		[_
FRACTURE TREAT		ULL OR ALTER CASING	-	WATER SHUT-OFF	1	REPAIRING W	15.7
SHOOT OR ACIDIZE		BANDON*	- .	PRACTURE TREATMENT	_	ALTERING CA	
REPAIR WELL		HANGE PLANS		SHOOTING OR ACIDISING	• —	ABANDONMEN	
(Other)	٠٠ ليبا			(Other) (Norm: Report r	esults of	multiple completion o	n Well
	E COMPLETED OPER	ATIONS (Clarrie state a	Il pontinent de	Completion or Re	ecompletic	n Report and Log form	n)
4-12-72	Squeezed	Gallup perfs	4977 to	5116 w/50 sx			
4-13-72	Cut 5 1/2	" casing off	@ 2015'	pulled same			
4-14-72	Spotted 5	n hole, spott 0 sx plug fro 0 sx plug fro	m 1350'		70' tá	1920'	
4-16-72	Set P&A	marker w/10	sx surf	ace plug			. ,
6-21-72	Clean up	location					
•			ار این		1 0	Ann	
I hereby centify that	2 a torrerate to	244	7		*		
			7				
SIGN (This space for Feder	yw	Y Y TIT	TUE Pr	esident		DATE Augus	t 2, 197

- Λ(f) = - 1972 - **P**. T. γ = μ = 100

を これでは、 これ

16

*See Instructions on Reverse Side

(MO) MO