

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SF 078953
Unit J. H. Goddard

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	RECEIVED MAY 28 1958 U.S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>Surface</u>	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 26, 1958

J. H. Goddard

Well No. 3 is located 2100 ft. from XXX line and 1560 ft. from W line of sec. 11

NE 1/4 - SW 1/4 Section 11
(1/4 Sec. and Sec. No.)

26N
(Twp.)

12W
(Range)

N.M.P.M.
(Meridian)

Undesignated (Gallup)
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)


The elevation of the derrick floor above sea level is 6068 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SPUDDED: 4:00 A.M., 4/25/58

Set 10-3/4" casing at 413', cemented with 450 sacks regular cement, 21 CaCl.
Cement circulated to surface.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY

Box 426

Address Farmington, New Mexico

By (Signed) E. A. Gosper

Title District Superintendent